

TPP Enterprises, LLC

Buckles Order Sheet

2016 Prices

Code	Description	Full Price	12+	60+	Quan
TPP-SR-BK050-KL	1/2" Black Locking	2.1	1.85	1.6	
TPP-SR-BK050-KN	1/2" Black Non-locking	1.25	1.1	0.9	
TPP-SR-BK050-NL	1/2" Nickel Locking	2	1.8	1.5	
TPP-SR-BK050-NN	1/2" Nickel Non-locking	1	0.9	0.75	
TPP-SR-BK050-NNF	1/2" Nickel Non-locking (faux roller)	0.75	0.7	0.6	
TPP-SR-BK050-BN	1/2" Brass Non-Locking	0.75	0.7	0.6	
TPP-SR-BK075-KL	3/4" Black Locking	2.5	2.25	2	
TPP-SR-BK075-KN	3/4" Black Non-locking	2	1.8	1.5	
TPP-SR-BK075-NL	3/4" Nickel Locking	2	1.8	1.5	
TPP-SR-BK075-NN	3/4" Nickel Non-locking	1.25	1.1	0.9	
TPP-SR-BK075-BN	3/4" Brass Non-Locking	2	1.8	1.5	
TPP-SR-BK075-BNF	3/4" Brass Non-Locking (Faux Roller)	1	0.9	0.75	
TPP-SR-BK100-KL	1.0" Black Locking	2.5	2.25	2	
TPP-SR-BK100-KN	1.0" Black Non-locking	2	1.8	1.5	
TPP-SR-BK100-NL	1.0" Nickel Locking	2.5	2.25	2	
TPP-SR-BK100-NN	1.0" Nickel Non-locking	1.5	1.35	1.2	
TPP-SR-BK100-NNF	1.0" Nickel Non-locking (faux Roller)	1	0.9	0.75	
TPP-SR-BK100-BL	1.0" Brass Locking	2.25	2	1.6	
TPP-SR-BK100-BN	1.0" Brass Non-Locking	2.25	2	1.6	
TPP-SR-BK100-BNF	1.0" Brass Non-Locking (Faux Roller)	1	0.9	0.75	
TPP-SR-BK125-KL	1.25" Black Locking	3	2.7	2.25	
TPP-SR-BK125-KN	1.25" Black Non-locking	2.25	2	1.6	
TPP-SR-BK125-NLF	1.25" Nickel Locking (Faux Roller)	2.5	2.25	2	
TPP-SR-BK125-NNF	1.25" Nickel Non-locking (Faux Roller)	2	1.8	1.5	
TPP-SR-BK125-BLF	1.25" Brass Locking (Faux Roller)	3.25	3	2.5	
TPP-SR-BK150-NL	1.5" Nickel Locking Buckle	3.5	3.15	2.5	
TPP-SR-BK200-NLDT	2.0" Nickel Double Tounge locking Buckle	3.75	3.4	3	
TPP-SR-BK001-NLPS	Lock Post with screw and Brass washer	2.05	1.75	1.6	
TPP-SR-BK002-NTLS	Twist lock with eyelet	5	4.25	3	
Total Buckles Ordered					0

Prices are Mix and Match and prices are subject to change.

Prices do NOT include shipping (shipping will be via reasonable lowest cost unless specified otherwise).

Quantities above 50 of any one item may require a special order.

Email Sales@PleasureParadox.com for formal invoice and availability.

Quantities above 12 will not be checked individually and a failure rate of 1 per 100 pieces is expected, replacements will be shipped with the next order if available.